

AIRWORTHINESS ADVICE NOTICE

- TYPE AFFECTED:** Stemme S-10, all models, all serial numbers.
- SUBJECT:** Miscellaneous airworthiness information.
- APPROVED MODS:**
1. Installation of cockpit fire extinguisher. Stemme Service Bulletin No A31-10-062 provides for the optional installation of a certified fire extinguisher in the cockpit.
 2. Cockpit sealing. Stemme Maintenance Instruction No A35-10-057D/E describes the cockpit sealing system used in newly-manufactured aircraft and provides for the upgrading of earlier models to the new standard.
- The above-mentioned documents are available from the GFA Secretariat on request.
- OTHER ITEMS:** A complete list of all ADs and Service Bulletins for all S-10 models was issued by the manufacturer on 23 July 2002 and copies are available from the GFA Secretariat on request.

SIGNED:



SENIOR TECHNICAL OFFICER AIRWORTHINESS

For and on behalf of:

**THE GLIDING FEDERATION
OF AUSTRALIA**